



Expansion Joint Failsafe System

INSPECTION DEPARTMENT

MONTHLY EXPANSION
JOINT FAILSAFE SYSTEM.

DATE: 2015.12.29.

NORTH WEST SIDE SPAN	ROCKER PLATE SPRINGS & PINS	FIXINGS	TONGUE PLATE SPRINGS & PINS
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
NORTH EAST SIDE SPAN			
S.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	2 no. CRACKED SPRINGS – REMAIN IN TENSION & SECURE
S.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
NORTH WEST MAIN SPAN			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
NORTH EAST MAIN SPAN			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH WEST SIDE SPAN			
S.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 2	SATISFACTORY	SATISFACTORY	CRACKED SPRING – REMAINS IN TENSION & SECURE
S.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.W. 6	SATISFACTORY	SATISFACTORY	CRACKED SPRING – REMAINS IN TENSION & SECURE
SOUTH EAST SIDE SPAN			
S.E. 1	SATISFACTORY	SATISFACTORY	CRACKED SPRING – REMAINS IN TENSION & SECURE
S.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
S.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH WEST MAIN SPAN			
M.W. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.W. 5	SATISFACTORY	SATISFACTORY	CRACKED SPRING – REMAINS IN TENSION & SECURE
M.W. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
SOUTH EAST MAIN SPAN			
M.E. 1	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 2	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 3	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 4	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 5	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.
M.E. 6	SATISFACTORY	SATISFACTORY	IN LOCATION AND SATISFACTORY.

Signed by Inspector :

New cracked spring found this inspection S.E 1 (West Spring)