

FETA. Suspended Structure Principal Inspection. (Main Span) MSNPI. 04.

Location / Area of Inspection: P.P. 46 to 53.5.		Sheet 1 of 1	
Element / Part / Item.	Defects Recorded. (Structure Number if Applicable)	Recording Inspector & Date.	Repairs Completed : Job Card / Insp / Date.
Deck Soffit.	None.	. 08/09/04	N/A
Trough Stiffeners.	None.	. 08/09/04	N/A
Stringers & Bearing Pads.	Bearing pads to Beam No1. (Minor corrosion & staining)	. 08/09/04	
Cross Girder Beams.	None.	. 08/09/04	N/A
Billets.	None.	. 08/09/04	N/A
Top Laterals.	None.	. 08/09/04	N/A
Bottom Laterals.	None.	. 08/09/04	N/A
Braking Girders.	None.	. 08/09/04	N/A
King Posts.	None.	. 08/09/04	N/A
Vertical Trusses.	None.	. 08/09/04	N/A
Diagonal Trusses.	None.	. 08/09/04	N/A
Top Chord (general).	None.	. 08/09/04	N/A
Bottom Chord (general).	P.P 47: has incomplete gasket,sealed with Sikaflex-11FC. (A.T.O.I.)	. 08/09/04	N/A
Top Chord (splice boxes).	Unpainted studs/nuts at P.P.48,50,52,54,56,&58. (Internal painting Comp)	. 08/09/04	
Bottom Chord (splice boxes).	Unpainted studs/nuts at P.P.47,49,51,53 & 55. (Internal painting Comp)	. 08/09/04	
Service Ducts & Conduits.	None.	. 08/09/04	N/A
Drains & Downpipes.	P.P.46 E&W, have wooden spacer fixed with rope.	. 08/09/04	
Line Walkway Supports.	None.	. 08/09/04	N/A
Line Walkway Decking.	None.	. 08/09/04	N/A
Crossover Steelwork & Deck Fasteners.	N/A	. 08/09/04	N/A
Cycle Track Soffit.	None.	. 08/09/04	N/A
Cycle Track Bearings.	None.	. 08/09/04	N/A
Hanger Rope Connections.	None.	. 08/09/04	N/A
Lamp Post Connections.	None.	. 08/09/04	N/A
Sign Post Connections.	None.	. 08/09/04	N/A
Runway Beam Connections.	None.	. 08/09/04	N/A
Grillages (underside).	None.	. 08/09/04	N/A
Paintwork (general).	None.	. 08/09/04	N/A
Corrosion (general).	Very minor stain indications evident, generally at mating faces.	. 08/09/04	
Miscellaneous:	General Comments: .	General Comment:	General Comment: