

INSPECTION DATES. : 10/12/08 & 15/12/08.

**MAINSpan (EAST) STRINGER DOUBLE PLATE
LOCATIONS.**

	SOUTH. EAST.		NORTH. EAST.
PP. 48.		PP. 100.	
PP. 50.		PP. 98.	Stringer no1.
PP. 52.		PP. 96.	
PP. 54.		PP. 94.	Stringer no1.
PP. 56.	Stringers no 1, 2, 3 & 4	PP. 92.	Stringer no1.
PP. 58.	Stringers no 1, 2, 3 & 4	PP. 90.	
PP. 60.	Stringer no 2	PP. 88.	Stringers no3&4.
PP. 61	Stringer no 3		
PP. 62.	Stringer no 1	PP. 86.	
PP. 64.		PP. 84.	Stringers no1&2
PP. 66.	Stringers no 1, 2 & 4	PP. 82.	
PP. 68.		PP. 80.	
PP. 70.	Stringers no 1, 2 & 4	PP. 78.	Stringers no1&2
PP. 72.	Stringer no 1	PP. 76.	Stringer no1.
PP. 74.	Stringer no 1	PP. 74.	
PP. 76.	Stringers no 1, 2, 3 & 4	PP. 72.	
PP. 78.	Stringers no 3 & 4	PP. 70.	Stringer no4.
PP. 80.	Stringers no 1 & 4	PP. 68.	Stringer no4.
PP. 82.	Stringers no 1, 2, 3 & 4	PP. 66.	
PP. 84.		PP. 64.	
PP. 86.		PP. 62.	
PP. 88.	Stringers no 1 & 2	PP. 60.	
PP. 90.		PP. 58.	Stringers no 1&2.
PP. 92.		PP. 56.	
PP. 94.		PP. 54.	Stringers no 1,2, 3 & 4.
PP. 96.		PP. 52.	Stringers no 1,2, 3 & 4.
PP. 98.		PP. 50.	
PP. 100.		PP. 48.	