



<b>INSPECTION DEPARTMENT</b>
<b>North S/ T roller bearing measurement chart.</b>
<b>DATE. 09/12/10.</b>

Temperatures taken at approx 09.15 am.  
Steel temperature at time of inspection. + 2.5 c

[illegible]



INSPECTION DEPARTMENT
North S/ T roller bearing measurement chart.
DATE. 09/12/10.