

INSPECTION DEPARTMENT

NORTH WEST SIDE TOWER POST TENSION SURVEY DATE: 26/05/11

SIDE TOWER POST TENSION CABLE SURVEY			
NORTH SIDE TOWER			BASE LEVEL
WEST	1 2 3 4	5 6 7 8	9 10
EAST 1 2 3 4 5 6 7 8 9 10			
E1 intact and secure.		W1 intact and se	ecure.
E2 intact and secure.		W2 intact and	secure.
E3 intact and secure.		W3 intact and s	secure.
E4 intact and secure.		W4 intact and s	secure.
E5 intact and secure.		W5 intact and s	secure.
E6 intact and secure.		W6 intact and se	ecure.
E7 intact and secure.		W7 intact and s	secure.
E8 intact and secure.		W8 intact and s	secure.
9 intact and secure.		W9 intact and secure.	
E10 intact and secure.		W10 intact and s	secure.
All post tension cables remain in No signs of moisture/water evidence.			
INSPECTOR:		DATE: 26/05/	11.
INSPECTOR:		DATE: 26/05/	