

SIDE TOWER POST TENSION CABLE SURVEY	
NORTH SIDE TOWER WE	ST LEG BASE LEVEL
WEST 1 2 3 4	5 6 7 8 9 10
EAST 1 2 3 4	5 6 7 8 9 10
E1 intact and secure.	W1 intact and secure.
E2 intact and secure.	W2 intact and secure.
E3 intact and secure.	W3 intact and secure.
E4 intact and secure.	W4 intact and secure.
E5 intact and secure.	W5 intact and secure.
E6 intact and secure.	W6 intact and secure.
E7 intact and secure.	W7 intact and secure.
E8 intact and secure.	W8 intact and secure.
E9 intact and secure. E10 intact and secure.	W9 intact and secure. W10 intact and secure.
Floor remains dry at time of inspection. Post tensioned cable information remains as annual inspection date 2013.04.11	
INSPECTOR:	DATE: 2014.05.28
INSPECTOR:	DATE: 2013.05.28

C:\Users\136377\Desktop\FETA inspection records for Side Towers\General Reports\General Report. No 433. Side towers N & S. 2014.05.28\North West Side Tower Post Tension Survey.doc



INSPECTION DEPARTMENT NORTH WEST SIDE TOWER POST TENSION SURVEY DATE: 2014.05.28.

C:\Users\136377\Desktop\FETA inspection records for Side Towers\General Reports\General Report. No 433. Side towers N & S. 2014.05.28\North West Side Tower Post Tension Survey.doc