




**INSPECTION DEPARTMENT** 

Pier top bearings.

DATE: 16/09/09.



Pin bearing at S/E 2.



Roller bearing at S/E 4.



Roller bearing at S/E 5



Roller bearing at S/E 6..



Roller bearing at S/E 7.

Created by GE.C:\Users\136377\Desktop\FETA inspection records of approach Viaducts\South\Principle Inspections\South Viaduct External PI 2009\Pier Top Bearings Sheet 1.doc





**INSPECTION DEPARTMENT** 

Pier top bearings.

DATE: 16/09/09.