





INSPECTION DEPARTMENT

Pier top bearings.

DATE : 16/09/09.








Pin bearing at S/E 3.



Roller & Pin bearing at S/E 3.



 $\label{eq:created} Created by GE.C:\Users\136377\Desktop\FEIA inspection records of approach Viaducts\South\Principle Inspections\South Viaduct External PI 2009\Pier Top Bearings Sheet 2.doc$





INSPECTION DEPARTMENT

Pier top bearings.

DATE : 16/09/09.