



Example of. Roller bearing.  
Heavy corrosion & Paint  
breakdown.



Paint breakdown &  
corrosion evident on Pin  
bearing.

All roller & pin bearings to be replaced under capital plan programme of works.

INSPECTION DEPARTMENT
Pier top bearings.
DATE : 16/09/09.