





WELD STATED AS NOT BROKEN, HAD BEEN CLEANED USING INTERNAL GRINDER, MAKING CRACK PLAINLY VISIBLE, AS OPPOSED TO COMMENT HIGHLIGHTED IN YELLOW.



**THE TWO WELDS EITHER
SIDE OF STRINGER NUMBER
2 HAVE VISABLE
INDICATIONS OF
HOLES/SLAG INCLUSIONS**