



# FORTH ESTUARY TRANSPORT AUTHORITY

## VISUAL WELD INSPECTION REPORT

Technician:	Inspection Qualification:	Date. : 2014.10.12.
Signature:	<b>P.C.N. LEVEL 2</b>	
Work Pack No. N/A	Drg No. <b>N/A</b>	Inspection Part: . <b>MW 3.</b> Rocker & Tongue plate bearing blocks.
Inspection Document Conforming To BSEN 13018:2001		
Direct Visual Test:	Aided	Unaided
If Aided:	Equipment:	
Remote Visual Test:	Endoscope	Fibre Optics
Test Location:	Workshop.	On site.
Illumination:	Natural	Auxiliary
Area Examined:	Welds & Heat Affected Zone	
Surface Condition:	As Welded	Dressed
Surface Preparation:	Dry & Free of all Dirt, Grease, Scale, Spatter, Oil etc.	
Fabrication Stage:	Fabrication Complete.	
Purpose of Test:	To find any surface breaking defects or indications.	
Name of Welder.: <b>N/A</b>	I.D. N/A	Results:
<u>Comments:</u>  It should be recorded that all Rocker & tongue plate bearing block fillet welds were visually inspected only. All welds remain in a satisfactory condition.		<u>Accept:</u>
		<u>Reject:</u>

Q:\E Engineering\E2 - Inspections\E2.1 Bridge\Joints\Main Tower Demag Expansion Joints\Independent Inspections\North west main tower expansion joint . MW3. 2014.10.12\Rocker & tongue plate welds plate MW3. 2014.10.12..doc