

# **General Inspection Report**

(BC13)

REPORT No.7

SIDE TOWER NORTH

DATE: 15/01/1997 TO 16/01/1997

The main cable saddles located at Both North East and North West side towers were visually inspected and found to be satisfactory with exception of a few very minor defects, these are noted in individual inspection reports.