

General Inspection Report

(BC13)

REPORT No.6

SIDE TOWER SOUTH

DATE: 15/01/1997 TO 16/01/1997

The main cable saddles located at Both South East and South West side towers were visually inspected and found to be satisfactory with exception of a few very minor defects, these are noted in individual inspection reports.