



INSPECTION DEPARTMENT
SOUTH WEST SIDE TOWER POST TENSION SURVEY
DATE: 2013.05.26.

SIDE TOWER POST TENSION CABLE SURVEY																					
SOUTH SIDE TOWER	WEST LEG																				
BASE LEVEL																					
<div style="border: 1px solid black; width: 80px; height: 30px; margin: 10px auto; text-align: center; line-height: 30px;">WEST</div> <div style="border: 1px solid black; width: 300px; height: 150px; margin: 20px auto; position: relative;"> <div style="position: absolute; top: 5px; left: 5px;"> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> </table> </div> <div style="position: absolute; bottom: 5px; left: 5px;"> <table border="1" style="border-collapse: collapse; text-align: center;"> <tr> <td>1</td><td>2</td><td>3</td><td>4</td><td>5</td><td>6</td><td>7</td><td>8</td><td>9</td><td>10</td> </tr> </table> </div> </div> <div style="border: 1px solid black; width: 80px; height: 30px; margin: 10px auto; text-align: center; line-height: 30px;">EAST</div>	1	2	3	4	5	6	7	8	9	10	1	2	3	4	5	6	7	8	9	10	<div style="border: 1px solid black; width: 80px; height: 30px; margin: 10px auto; text-align: center; line-height: 30px;">NORTH →</div>
1	2	3	4	5	6	7	8	9	10												
1	2	3	4	5	6	7	8	9	10												
E1 1 OFF STRAND SEVERED.	W1 HEAVY CORROSION.																				
E2 1 OFF STRAND SEVERED.	W2 HEAVY CORROSION.																				
E3 HEAVY CORROSION.	W3 HEAVY CORROSION.																				
E4 HEAVY CORROSION.	W4 HEAVY CORROSION.																				
E5 HEAVY CORROSION.	W5 HEAVY CORROSION.																				
E6 HEAVY CORROSION.	W6 HEAVY CORROSION.																				
E7 HEAVY CORROSION.	W7 HEAVY CORROSION.																				
E8 HEAVY CORROSION.	W8 HEAVY CORROSION.																				
E9 HEAVY CORROSION.	W9 HEAVY CORROSION.																				
E10 HEAVY CORROSION.	W10 HEAVY CORROSION.																				
<p>Water on floor at time of inspection.</p> <p>Small sump at base level full at time of inspection.</p> <p>No further breakages since previous inspection carried out. 2013.04.12..</p>																					
INSPECTOR:	DATE: 2014.05.26.																				
INSPECTOR:	DATE: 2013.05.26.																				

C:\Users\136377\Desktop\FETA inspection records for Side Towers\General Reports\General Report. No 433. Side towers N & S. 2014.05.28\South West Side Tower Post Tension Survey.doc



INSPECTION DEPARTMENT
SOUTH WEST SIDE TOWER POST TENSION SURVEY
DATE: 2013.05.26.

C:\Users\136377\Desktop\FETA inspection records for Side Towers\General
Reports\General Report. No 433. Side towers N & S. 2014.05.28\South West Side Tower
Post Tension Survey.doc