





INSPECTION DEPARTMENT
Trough defects. South East & West main-span.
DATE. 12/06/12.

South East


Between PP.70-71 . Weld crack Trough No 2 . approx 100mm long.




Between PP.70-71 . Weld crack Trough No 2. approx 250 mm long.



Between PP. 75-76. Weld crack Trough No 1 . approx 50 mm long.



Between PP.83-84. Weld crack , Trough No 2 . approx 75 mm long.





INSPECTION DEPARTMENT
Trough defects. South East & West main-span.
DATE. 12/06/12.

South West

Between PP.55-56. Weld crack , Trough No 2 . approx 100 mm long.

