



INSPECTION DEPARTMENT
Viaduct Soffit Survey Sheet
DATE: January 2015

West cycle track		East cycle track	
			BI13
			BI14
			BI15
			BI16

Beam Numbers

Heavy water staining and spalling 0.4 x 0.3 approx