



INSPECTION DEPARTMENT
Viaduct Soffit Survey Sheet
DATE: January 2015

West cycle track		East cycle track	
			B86X
		<div>0.5 x 0.3 approx</div>	B87X
		<div>0.4 x 0.4 approx</div>	B88X
			B89X

Beam Numbers