





INSPECTION DEPARTMENT
Viaduct Soffit Survey Sheet
DATE: January 2015

West cycle track				East cycle track	
					B96
Heavy water staining					B97
 					
0.4 x 0.2 approx					B98
					B99

Beam Numbers