



P.P.95 – 96 N.W.

1. Longitudinal crack approx. 600mm long.
2. Potential new crack start point, unable to determine without closer inspection.
Ensure staging is large enough to encompass No. 2 potential defect.